



Indian Point Energy Center
450 Broadway, GSB
P.O. Box 249
Buchanan, N.Y. 10511-0249
Tel (914) 734-6700

J. E. Pollock
Site Vice President

NL-10-110

November 2, 2010

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Stop O-P1-17
Washington, D.C. 20555-0001

SUBJECT: Licensee Event Report # 2010-007-00, "Automatic Reactor Trip Due to a Turbine Trip as a Result of a High Steam Generator Level Trip After Transition to Single Feedwater Pump Operation"
Indian Point Unit No. 2
Docket No. 50-247
DPR-26

Dear Sir or Madam:

Pursuant to 10 CFR 50.73(a)(1), Entergy Nuclear Operations Inc. (ENO) hereby provides Licensee Event Report (LER) 2010-007-00. The attached LER identifies an event where the reactor was automatically tripped, which is reportable under 10 CFR 50.73(a)(2)(iv)(A). As a result of the reactor trip, the Auxiliary Feedwater System was actuated, which is also reportable under 10 CFR 50.73(a)(2)(iv)(A). This condition was recorded in the Entergy Corrective Action Program as Condition Report CR-IP2-2010-05484.

There are no new commitments identified in this letter. Should you have any questions regarding this submittal, please contact Mr. Robert Walpole, Manager, Licensing at (914) 734-6710.

Sincerely,

A handwritten signature in black ink, appearing to read "JEPollock".

JEP/cbr

cc: Mr. William Dean, Regional Administrator, NRC Region I
NRC Resident Inspector's Office, Indian Point 2
Mr. Paul Eddy, New York State Public Service Commission
LEREvents@inpo.org

JE22
NRR

LICENSEE EVENT REPORT (LER)

Estimated burden per response to comply with this mandatory collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME: INDIAN POINT 2

2. DOCKET NUMBER
05000-2473. PAGE
1 OF 6

4. TITLE: Automatic Reactor Trip Due to a Turbine Trip as a Result of a High Steam Generator Level Trip After Transition to Single Feedwater Pump Operation

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED																																					
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV. NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER																																				
9	3	2010	2010-	007	- 00	11	2	2010	FACILITY NAME	DOCKET NUMBER 05000																																				
9. OPERATING MODE 1			11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)																																											
10. POWER LEVEL 41%			<table border="0"><tr><td><input type="checkbox"/> 20.2201(b)</td><td><input type="checkbox"/> 20.2203(a)(3)(i)</td><td><input type="checkbox"/> 50.73(a)(2)(i)(C)</td><td><input type="checkbox"/> 50.73(a)(2)(vii)</td></tr><tr><td><input type="checkbox"/> 20.2201(d)</td><td><input type="checkbox"/> 20.2203(a)(3)(ii)</td><td><input type="checkbox"/> 50.73(a)(2)(ii)(A)</td><td><input type="checkbox"/> 50.73(a)(2)(viii)(A)</td></tr><tr><td><input type="checkbox"/> 20.2203(a)(1)</td><td><input type="checkbox"/> 20.2203(a)(4)</td><td><input type="checkbox"/> 50.73(a)(2)(ii)(B)</td><td><input type="checkbox"/> 50.73(a)(2)(viii)(B)</td></tr><tr><td><input type="checkbox"/> 20.2203(a)(2)(i)</td><td><input type="checkbox"/> 50.36(c)(1)(i)(A)</td><td><input type="checkbox"/> 50.73(a)(2)(iii)</td><td><input type="checkbox"/> 50.73(a)(2)(ix)(A)</td></tr><tr><td><input type="checkbox"/> 20.2203(a)(2)(ii)</td><td><input type="checkbox"/> 50.36(c)(1)(ii)(A)</td><td><input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)</td><td><input type="checkbox"/> 50.73(a)(2)(x)</td></tr><tr><td><input type="checkbox"/> 20.2203(a)(2)(iii)</td><td><input type="checkbox"/> 50.36(c)(2)</td><td><input type="checkbox"/> 50.73(a)(2)(v)(A)</td><td><input type="checkbox"/> 73.71(a)(4)</td></tr><tr><td><input type="checkbox"/> 20.2203(a)(2)(iv)</td><td><input type="checkbox"/> 50.46(a)(3)(ii)</td><td><input type="checkbox"/> 50.73(a)(2)(v)(B)</td><td><input type="checkbox"/> 73.71(a)(5)</td></tr><tr><td><input type="checkbox"/> 20.2203(a)(2)(v)</td><td><input type="checkbox"/> 50.73(a)(2)(i)(A)</td><td><input type="checkbox"/> 50.73(a)(2)(v)(C)</td><td><input type="checkbox"/> OTHER</td></tr><tr><td><input type="checkbox"/> 20.2203(a)(2)(vi)</td><td><input type="checkbox"/> 50.73(a)(2)(i)(B)</td><td><input type="checkbox"/> 50.73(a)(2)(v)(D)</td><td></td></tr></table> <p>Specify in Abstract below or in NRC Form 366A</p>								<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	
<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)																																											
<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)																																											
<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)																																											
<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)																																											
<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)																																											
<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)																																											
<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)																																											
<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER																																											
<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)																																												

12. LICENSEE CONTACT FOR THIS LER

NAME	TELEPHONE NUMBER (Include Area Code)
Robert Sergi, I&C Design Engineer	(914) 827-7765

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX
X	JK	FC	N430	Y	X	JB	LC	N430	Y

14. SUPPLEMENTAL REPORT EXPECTED

☐ YES (If yes, complete 15. EXPECTED SUBMISSION DATE) ☒ NO

15. EXPECTED SUBMISSION DATE

MONTH DAY YEAR

16. ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced type written lines)

On September 3, 2010, during a scheduled plant shutdown, an automatic reactor trip (RT) was initiated as a result of a turbine trip due to a high steam generator (SG) water level. All control rods did not indicate fully inserted as the Individual Rod Position Indicator (IRPI) for rod H-8 indicated 38 steps withdrawn and its rod bottom light failed to light. Rod H-8 was verified to be fully inserted by alternate means. All primary systems functioned properly. The plant was stabilized in hot standby with decay heat being removed by the main condenser. The Auxiliary Feedwater System automatically started as designed due to automatic trip of the MBFPs as a result of closure of the MBFP discharge valves from the SG high level trip. The direct cause of the RT was a turbine trip on a high SG level. The root cause was inadequate design control of the proportional band and reset tuning settings for critical plant controllers. There was less than optimum controller settings on the MBFP speed controller, Feed Regulatory Valve (FRV) flow controllers, and the SG level controllers for low power operation. Significant corrective actions include: I&C procedures developed from I&C Preventive Maintenance documents have been reviewed to ensure that the instrument calibration requirements have been transferred into the I&C procedures, a list of critical controllers was generated and the Equipment Data Base (EDB) updated with known existing settings, I&C procedures will be reviewed to identify changes to ensure controller calibrations maintain required settings and procedures will be revised to incorporate testing of critical parameters, an engineering evaluation will be issued and the EDB updated in the work control program with findings on controller settings. The event had no effect on public health and safety.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
Indian Point Unit 2	05000-247	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 6
		2010	- 007	- 00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

Note: The Energy Industry Identification System Codes are identified within the brackets {}.

DESCRIPTION OF EVENT

On September 3, 2010, at 10:58 hours during a scheduled plant shutdown for a forced outage, while at approximately 41% reactor power, an automatic reactor trip (RT) {JC} was initiated as a result of turbine trip (TT) due to a steam generator (SG) {AB} high water level {JB}. All control rods {AA} did not indicate fully inserted as the Individual Rod Position Indicator (IRPI) for rod H-8 indicated 38 steps withdrawn and its rod bottom light failed to light. Rod H-8 was verified to be fully inserted by alternate means. All primary systems functioned properly. The plant was stabilized in hot standby with decay heat being removed by the main condenser {SG}. The Auxiliary Feedwater Pumps (AFWP) {BA} automatically started as designed due to automatic trip of the Main Boiler Feedwater Pumps (MBFPs) {SJ} as a result of closure of the MBFP discharge valves from the SG high level trip. The event was recorded in the Indian Point Energy Center corrective action program (CAP) as CR-IP2-2010-05484. A post trip evaluation was initiated and authorization for restart completed on September 10, 2010.

Prior to the event the unit was operating with a high upper bearing temperature for the 21 reactor coolant pump (RCP) motor {AB}. At approximately 08:00 hours, operations commenced turbine load reduction for a scheduled plant shutdown to repair the 21 RCP motor. Power was reduced from 100% to approximately 41% between 08:00 to 10:30 hours. During this time both MBFPs were in operation (AUTO) with stable steam flow, Feedwater (FW) flow and SG level. At approximately 10:54 hours, the 21 MBFP (lead pump) was removed from service (approximately 6000 gpm to 3300 gpm in approximately 60 seconds). The 22 MBFP increased in speed to make up for the 21 MBFP being removed from service. However, the loss of FW flow to the SGs was not made up by the 22 MBFP immediately. There was a period of approximately two minutes following the securing of the 21 MBFP where total FW flow was reduced and resulted in a decrease in level in all four SGs. The 22 MBFP speed increased to restore SG water level to the controller setting. FW flow remained below the initial stable flow for approximately one minute with SG level decreasing. The 22 MBFP continued to increase in speed and flow when SG level began to recover. Subsequently, SG level returned to the original level but MBFP speed and FW flow were elevated further increasing SG level. In response to increasing SG level operators placed the 24 Feed Regulation Valve (FRV) in manual control to reduce FW flow. Approximately 30 seconds after operators took manual control of the 24 FRV, the 22 and 23 FRV responded in AUTO and started reducing FW to their associated SGs. SG level was continuing to increase in SG 21, 22 and 23 but the level in SG 24 started to reduce. Operations initiated manual control of the 21 FRV and reduced FW flow to the 21 SG which resulted in increased FW flow to the other SGs (22, 23 and 24). Subsequently the water level in the 23 SG reached the high level trip setpoint (73%) and a turbine trip on SG high level was initiated. A high SG level on two out of three level transmitters on any SG results in the automatic actuation of the following: 1) generator trip (86P and 86BU relays), 2) closure of the main and low flow FRVs, 3) closure of the MBFP discharge valves, and a turbine trip which results in a RT. Closure of the MBFP discharge valves causes both MBFPs to trip. An automatic trip of either MBFP will initiate an automatic start of the AFWPs.

Following the unit trip, an investigation of the event was initiated. The investigation focused on response of the SG Water Level Control (SGLC) system {JB} for maintaining level and MBFP speed, and the greater than expected loss of FW flow associated with removing a MBFP from service at low power levels.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Indian Point Unit 2	05000-247	2010	- 007	- 00	3 OF 6

The SGWLC system consists of four three element control configurations, one for each SG, to control the position of its associated FRV. The SGWLC system senses steam flow and FW flow mismatch and deviation from level set point and sends a signal to the FRV positioners to modulate the FRVs. The controllers in the three element control system include dynamic response actions as well as static gain settings (Proportional Band). The gain produced changes in the controller outputs are modified by the total time that the sensed parameters are not on setpoint; this being the influence of Reset or Integral action. This occurs in both the level control (LC) and flow control (FC) sections of the three element control configuration. A total demand signal is then sent to components that adjust FRV stroke, thereby positioning them as required by the control system. The system can be tuned to one set of response coefficients (i.e., proportional Band and Integral). The three element control tuning is setup for 100% steady state load which is the prevailing condition, and anticipated plant upsets that occur at and near full load conditions. Engineering concluded the FRV control system responded as expected based on the existing tuning of the system with a reset time of 90 seconds. Engineering determined that although the settings were acceptable, FW Three-Element Controllers FC-417, FC-427, FC-437 and FC-447, and SG Level Controllers (LC) LC-417M, LC-427M, LC-437M and LC-447M have settings which are not optimum for controlling FW and SG level transients during plant shutdowns because they are tuned for 100% power conditions. The SGWLC system uses proportional and integral controllers {JB} manufactured by NUS Corporation. The SG Level Controllers {LC} are manufactured by NUS {N430}, Model number PIDA700 controllers. The SG FW Flow Controllers (FC) are manufactured by NUS, Model number PIDA700 controllers.

The MBFP speed control program {JK} is designed to provide fixed differential pressure (dp) across FRVs between 0% and 100% power. The fixed dp actually available to the FRVs is the dp values minus static head and frictional losses. Tuning settings for common speed controller FC-419 included a 60 second lag in the plant load input to the MBFP speed control program to allow the SGWLC system to respond to steam flow changes. Controller performance requirements of FC-419 should have tuning settings of 250% Proportional Band (PB) (Gain equal to 0.4) and a reset (Integral) time of 90 sec. Tuning settings of FC-419 following the event were found to be 1000% PB (Gain equal to 0.1) and a reset of 21.6 seconds. The As-Found settings of FC-419 would have an initial effect of slower response from the 22 MBFP. The low gain condition of FC-419 is the reason for the initial slow response of MBFP 22 after the 21 MBFP was unloaded. As SG level controls drove the FRVs open, the FRVs dp was being challenged due to the slowed initial speed response from the 22 MBFP. The less than optimum settings of FW controllers and SG level controllers combined with the incorrect settings found on MBFP speed controller FC-419, resulted in the plant trip on high SG level. The MBFP speed control signal generator FC-419 {JK} is manufactured by NUS corporation {N430}, model number PIAD700.

Extent of condition review determined that the condition is applicable to unit 3 which recorded a similar event in CR-IP3-2009-2494 for a RT on May 28, 2009 at 61% power due to SG high level during power reduction. Inadequate controller settings are applicable to other unit 2 and 3 controllers. As a result of complications from the unit 3 May 28, 2009 RT, a combined CR-IP3-2009-2710 was initiated and it addresses critical controller settings and established Design Engineering as the responsible organization for control of critical controller settings.

Cause of Event

The direct cause of the RT was a turbine generator trip due to a high 23 SG level. The root cause was inadequate design control of the proportional band and reset tuning settings for critical plant controllers. There was less than optimum controller settings on the MBFP speed controller, FW controllers, and the SG level controllers for low power operation.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
Indian Point Unit 2	05000-247	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4 OF 6
		2010	- 007	- 00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

The following significant contributing causes (CC) were identified: CC1: Vague procedural guidance for securing the FW system at low power operations coupled with a human performance issue regarding the rate at which the speed was manually reduced on the 21 MBFP. Removing the 21 MBFP from service at a slower rate would have provided the 22 MBFP with a longer response time. The longer response time would allow the 22 MBFP more time to respond to the change in FW flow from the 21 MBFP and more closely match the change in FW flow. CC2: Untimely corrective action from previous root cause analysis (RCA). CR-IP3-2009-2710 included a RCA for a unit 3 automatic RT due to a high 32 SG level and engineering evaluated the optimum settings for SG level controllers (LC-417M, LC-427M, LC-437M and LC-447M) and FRV controllers (FC-417, FC-427, FC-437 and FC-447) for both units 2 & 3. The implementation of the recommended optimum settings have not been completed for either unit.

Corrective Actions

The following corrective actions have been or will be performed under Entergy's Corrective Action Program to address the cause and prevent recurrence:

- I&C procedures that have been developed from I&C Preventive Maintenance (ICPM) documents have been reviewed to ensure that the instrument calibration requirements documented in the ICPM have been transferred into the applicable I&C procedures.
- A list of unit 2&3 critical controllers was generated, and the Equipment Data Base was updated with known existing settings.
- Procedure 2-SOP-21.1 (Main FW System) was revised to provide guidance to operators to decrease MBFP speed slowly over a ten minute period when securing a MBFP to minimize SG level perturbations.
- I&C procedures will be reviewed to identify changes to ensure controller calibrations maintain required settings.
- I&C procedures will be revised to incorporate testing of critical parameters.
- An Engineering Evaluation will be issued and the Equipment Data Base updated in the IPEC work control program (IAS Passport) with findings on controller settings information based on conclusions of extent of condition evaluation.
- An engineering change (EC) will be prepared for both units 2 & 3 to revise SG control system controller mode settings to the engineering determined optimum mode setting for the FRV controllers (FC-417, FC-427, FC-437 and FC-447). The EC will include optimized mode settings for the SG level controllers (LC-417M, LC-427M, LC-437M and LC-447M).
- An inspection will be performed at units 2&3 of other critical controllers to collect data on existing proportional band and reset values.
- Operations procedures for plant shutdown at low power will be revised as necessary based on a review of the event.
- The MBFP speed controller FC-419 proportional band and reset timing settings have been reset to accepted engineering values.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Indian Point Unit 2	05000-247	2010	- 007	- 00	5 OF 6

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

Event Analysis

The event is reportable under 10CFR50.73(a)(2)(iv)(A). The licensee shall report any event or condition that resulted in manual or automatic actuation of any of the systems listed under 10CFR50.73(a)(2)(iv)(B). Systems to which the requirements of 10CFR50.73(a)(2)(iv)(A) apply for this event include the Reactor Protection System (RPS) including RT and AFWS actuation. This event meets the reporting criteria because an automatic RT was initiated at 10:58 hours, on September 3, 2010, and the AFWS actuated as a result of the SG high level condition. On September 3, 2010, at 13:11 hours, a 4-hour non-emergency notification was made to the NRC for an actuation of the reactor protection system (JC) while critical and included an 8-hour notification under 10CFR50.72(b)(3)(iv)(A) for a valid actuation of the AFW System (Event Log #46229). As all primary safety systems functioned properly there was no safety system functional failure reportable under 10CFR50.73(a)(2)(v).

Past Similar Events

A review was performed of the past three years for Licensee Event Reports (LERs) reporting a RT from a TT due to a SG high level or FW flow malfunctions. No LERs were identified that reported high SG level initiated RTs. There were three LERs that reported RTs caused by malfunctions of MBFPs that resulted in decreasing SG levels. LER-2008-001 reported a RT due to decreasing SG levels caused by decreasing MBFP speed as a result of radio frequency interference from camera use near the MBFP speed control processor. LER-2008-003 reported a RT due to decreasing SG levels caused by a turbine runback due to a failed MBFP runback circuit bistable with the control switch mispositioned to Armed. LER-2009-002 reported a RT due to decreasing SG levels caused by a loss of the 21 MBFP and failure of the main turbine to automatically runback. The 21 MBFP failure was due to a failed autostop oil line. These LERs did not have similar causes to this LER therefore their corrective actions would not have prevented this event.

Safety Significance

This event had no effect on the health and safety of the public. There were no actual safety consequences for the event because the event was an uncomplicated reactor trip with no other transients or accidents. Required primary safety systems performed as designed when the RT was initiated. The Auxiliary Feedwater System (AFWS) (BA) automatically started as designed due to automatic trip of the MBFPs as a result of closure of the MBFP discharge valves from the SG high level condition.

There were no significant potential safety consequences of this event under reasonable and credible alternative conditions. The RPS is designed to actuate a RT for any anticipated combination of plant conditions including a direct RT on TT unless the reactor is below approximately 20% power (P-8). The analysis in UFSAR Section 14.1.8 concludes an immediate RT on TT is not required for reactor protection. A RT on TT is provided to anticipate probable plant transients and to avoid the resulting thermal transient. If the reactor is not tripped by a TT, the over temperature delta temperature (OTDT) or over power delta temperature (OPDT) trip would prevent safety limits from being exceeded. During this event the SG level control system functioned as designed and initiated a TT. A RT and the increase in SG level is a condition for which the plant is analyzed.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
Indian Point Unit 2	05000-247	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	6 OF 6
		2010	- 007	- 00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

This event was bounded by the analyzed event described in FSAR Section 14.1.10, "Excessive Heat Removal Due to Feedwater System Malfunctions." Excessive FW additions is an analyzed event postulated to occur from a malfunction of the FW control system or an operator error which results in the opening of a FW control valve. The analysis assumes one FW valve opens fully resulting in the excessive FW flow to one SG. For the FW system malfunction at full power, the FW flow resulting from a fully open control valve is terminated by the SG high level signal that closes all FW control valves and trips the MBFPs. Trip of the MBFPs automatically actuates the AFWS. The SG high water level signal also produces a signal to trip the main turbine. A TT initiates a RT. The analysis for all cases of the excessive FW addition initiated at full power conditions with and without automatic rod control, show that the minimum DNBR remains above the applicable safety analysis DNBR limit, the primary and secondary side maximum pressures are less than 110% of the design values, and all applicable Condition II acceptance criteria are met.

For this event, rod control was in automatic. All control rods did not indicate fully inserted as the Individual Rod Position Indicator (IRPI) for rod H-8 indicated 38 steps withdrawn and its rod bottom light failed to light. Rod H-8 was verified to be fully inserted by alternate means. Troubleshooting determined that two electrolytic capacitors of IRPI required replacement. The AFWS actuated and provided required FW flow to the SGs. RCS pressure remained below the set point for pressurizer PORV or code safety valve operation and above the set point for automatic safety injection actuation. Following the RT, the plant was stabilized in hot standby.